



Product : WH Imaging Mammo 23 Mammography Unit

Quote: N/A

User: Smith, Jane

Phone: (555) 123-4567

Request: 875645

Client: ABC Health

Email: janesmith@abchealth.org

Date: 6/5/2023

Available Equipment Options

Option 1



Exact

Manufacturer: WH Imaging
Product: Mammography Unit
Model: Mammo 23
Year: 2012
Condition: Refurbished - Patient Ready
Warranty: 1 Year
Available: Now
Quantity: 1
Includes: Workstation, paddles & phantom
Notes: Fully tested & calibrated to OEM specifications
Price (ea.): \$42,500

Option 2



Exact

Manufacturer: WH Imaging
Product: Mammography Unit
Model: Mammo 23
Year: 2010
Condition: Refurbished - Patient Ready
Warranty: 1 Year
Available: Now
Quantity: 1
Includes: Workstation, paddles & phantom
Notes: Detector replaced 2014
Price (ea.): \$39,500

Option 3



Similar

Manufacturer: WH Imaging
Product: Mammography Unit
Model: Mammo 23
Year: 2011
Condition: As-Is - Where is
Warranty: 60 Days
Available: Now
Quantity: 1
Includes: Workstation, paddles
Notes: New detector
Price (ea.): \$21,500

Questions? Contact Miga Client Experience ✉ client@migasolutions.com 📞 (763) 225-8410.

Equipment Requested

Specifications

Manufacturer:	WH Imaging	Quantity:	1
Product:	Mammography Unit	Software Version:	Not provided
Model:	Mammo 23	Reason:	Supplemental
Age:	Any		
Other:	Must be refurbished & include workstation, paddles, and phantom		

Purchase Requirements

Match Required: Exact
Emergency: No
Budget: \$50,000
Date Needed: 60 days

This report and its contents are confidential and intended solely for use by registered EVMS users. Copying, distributing or the use in any form, by any party other than as expressly permitted in the EVMS Subscription Agreement is prohibited.